

Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe

Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

The Den, 208 Seabank.6

Certificate Reference

Certificate No: Na727

| Engineers Details | | | | | | | | lation E | Details | | | | Client D | etails | | | | | | |
|--|--|---------------------------------------|-------|------------|---------------------|----------------|---------------------------------------|---|--|------------------|--|------------------------|---------------------------------------|--|--|---|--|--------------------------------------|--------------------------------------|--|
| Trading Title Address | | JWPH (nw) Ltd 14 Seaview Ave Eastham | | | | | | llation | Steph Evans The Den 208 Seabank Rd | | | | | Client | Mr D | Dean | | | | |
| | | | | | | | | ess | | | | | | Address | S 18 Ju | bilee Drive | | | | |
| | | | | | | | | ĺ | | | | | | | West | West Kirby | | | | |
| | | Wirral | | | | | | | New Brighton | | | | | | Wirra | I | | | | |
| | | Post Code: CH62 0BD | | | | | | | Post Code: CH45 5AQ | | | | | | | Post Code: CH48 5EF | | | | |
| Gas | s Safe No: | 512904 Telephone No: 07939323244 | | | | | | Telephone No: | | | | | | Telephone No: | | 07770808889 | | | | |
| Appliance Details | | | | | | | | Inspection Details | | | | | | | | | | | | |
| | Locatio | Location | | nce Type | Make | Model | Combustion LOW (CO2% or CO/CO2 ratio) | Combustion HIGH (CO2% or CO/CO2 ratio) | Heat Input (KW) or Operating Pressure | CO Reading (ppm) | Appliance Inspected (YES/NO/NA/VIO) (WD = Vesual Improdor Only) | FlueType (OF/RS/FL) | Landlords Appliance (YES/NO/NA) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA) | Flue Performance Test (PASS/FAIL/NA) | Appliance Serviced (YES/NO/NA) | Appliance Safe To Use (YES/NO) | |
| 1 | Bed Ro | Bed Room | | nbi boiler | Heat line | Capriz2 24c | 0.0007 | 9.3 | 20.5 mb | 69 | YES | RS | YES | YES | YES | YES | PASS | NA | YES | |
| 2 | Kitche | Kitchen | | Oven | Beko | Ksg580 | null | null | 21.5 mb | Na | YES | FL | YES | YES | YES | NA | NA | NO | YES | |
| 3 | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | |
| Fa | ults/Notes | | | | L | Rem | Remedial Work Taken | | | | | | | | | Warning Notice Fixed | | | | |
| 1 | Cooker hose situated too low | | | | | | | | None | | | | | | | | | NA | | |
| 2 | Gas pipe not sealed and sleeved through wall | | | | | | | | | | | | | | | | | NA | | |
| 3 | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | |
| | ergency Cont essible: | rol Valve | · [| YES | Gas Tightness Sat | isfactory: YES | nature | Gas id Nulliber. | | | | | | | | | 512904 | | | |
| Gas Installation Pipework Visual Inspection Satisfactory: YES Nam | | | | | | | | | rt Issued By: Example 2: James Oliver Signed: Date: | | | | | | | | Tue-19-12-2023 | | | |
| Nun | nber of Appli | ances Te | sted: | 2 | Equipotential E | Bonding: YES | | t Received By: | | | | | | | 100 10 12 2020 | | | | | |
| NEXT INSPECTION DUE ON OR BEFORE: Sun-21-12-2025 Installation Pass: YES | | | | | |] Nan | _ | nr d dean Sign | | | | d: 🔀 | | = | Date: | Tue-19- | -12-2023 | | | |
| | Alarm fitted 8 | & working | g? [| YES Sr | moke alarm fitted & | & working? YES |] | | This Gas Safety Report was created by Gas Checker Software all rights reserved, www.gaschecker.co.uk | | | | | | | | | | | |